	A	В	С	D	E	F
1	## North America Emission Control Area Fuel Oil Non-Availability Report					
2	## ECA0100					
3	## 1	2	3	4	5	6
4	##					
5	##(Include Double Pound for comments, not form fields)					
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice
7	ECA0100	Chellaram Shipping Hong Kong Itd	Darya Jamuna	HK	9601948	1/16/2016

	G	Н	1	J	К
1					
2					
3	7	8	9	10	11
4					
5					
6	Location of ECA First Notice	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
7	3617N,07056W	Newport News	Ceuta	NA	NA

	L	M	N	0	Р	Q
1						
2						
3	12	13	14	15	16	17
4						
5						
6	Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
7	NA	1/16/2016	18:30	1.79	24	NEWPORT NEWS

	R	S	Т	U	V
1					
2					
3	18	19	20	21	22
4					
5					
6	Compliance Fuel Oil Available at First POC?	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
7	YES	NO	Vessel having compliant fuel oil onboard		

	W	X	Υ	Z
1				
2				
3	23	24	25	26
4				
5				
6	Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
7			1/22/2016	12:00

	AA	AB	AC	AD	AE	
1						
2						
3	27	28	29	30		31
4						
5						
6	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports	
7	No	1	NA	No		1

	AF	AG	AH
1			
2			
3	32	33	34
4			
5			
		Designated Corporate Official E-mail	Designated Corporate Official Phone Number
7	Capt. Swapan Kumar Majumdar onbehalf of Technical	technical@chellship.com	85229736111

	Al
1	
2	
3	35
4	
5	
6	Description of Actions to Achieve Compliance
7	Vessel is having sufficient quantity of ECA compliant LSMGO onboard, vessel successfully changed over to LSMGO, vessel not responding properly on trying out ahead and astern. As per Makers advise owners arranged spares at Newport News